

Part Number Update

Bulletin No: PNU-015-000-A

Effective Date: 5/15/98

Cancels: N/A

Page: 1 of 1

Subject: PART NUMBER SUPERSESSION

Effective May 15, 1998, the following Bendix manual slack adjuster will be superseded:

Current Part Number	Description	Replacement Part Number
103345	PL-20 Manual Slack Adjuster, 1-1/2"- 28 spline, 5", 6" clevis hole measurements	286965

There is no price impact with this change. The only difference between the part numbers is, the 103345 has a 90° grease zerk fitting and the 286965 has a straight grease zerk fitting.

Part number 235342 is a 90° grease zerk fitting only, which can be ordered if necessary.

