

Technical Bulletin

Bulletin No.: PRO-09-03 Effective Date: 7/20/77 Page: 1 of 1

Subject: **FD-1 Fan Clutch Bearing & Retainer / Piston Assembly Replacement**

Reference: Catalog Page 09-A-1

A recent revision has changed the material of the Fan Clutch piston from aluminum to cast iron, and changed the method of retaining the bearing to the piston from loctite to a lock nut. The piece numbers of the assemblies did not change.

Concurrent with this revision, the piece number of the spacer was changed from 291467 to 292622.

Upon replacement of the aluminum piston with a cast iron piston, the new spacer 292622 must be used. We therefore recommend that spacer 292622 be furnished along with 288921, 288922, 288923, and 288924 Bearing and Retainer / Piston Assembly.

