

# Part Number Update

Bulletin No: PNU-016-000-A

Effective Date: 9/1/98

Cancels: N/A

Page: 1 of 1

**Subject: MV-3 SERVICE P/N'S TO BE SUPERSEDED AND OBSOLETE  
SEPT 1<sup>ST</sup> 1998.**

The new service Part Number incorporates 2 changes in the MV-3 body.

- Improved double check valve design
- The new body will provide a ¼ - 18 NPT compared to the male exhaust stem on the current MV-3 body. An adapter is included for ease of service replacement.

Old Service P/N	Old OE P/N	New OE P/N	Customer ID	New Service P/N
65156	107218	5005051	-	<b>800515</b>
65156	5002205	5005052	Mack	<b>800515</b>
65157	106331	5005053	-	<b>800516</b>
65157	106992	5005054	Navistar	<b>800516</b>
65159	107214	5005055	Kenworth	<b>800517</b>
65160	107212	5005056	-	<b>800518</b>
65186	107220	5005057	Volvo	<b>800519</b>
65186	5000286	5005058	Western Star	<b>800519</b>
65187	107433	5005059	Freightliner	<b>800573</b>
65192	107467	5005060	Ford	<b>800521</b>
65208	106981	5004463	Mack	<b>800522</b>
65248	107753	5005062	Peterbilt	<b>800523</b>
65304	5004732	5005063	-	<b>800545</b>
65305	107215	5005064	Kenworth	<b>800525</b>
65379	108825	5005055	Kenworth	<b>800517</b>
65496	109325	5005066	Ford	<b>800527</b>
800082	5000884	5005067	Navistar	<b>800520</b>
800087	5000815	5005068	Freightliner	<b>800529</b>
800145	5002197	5005069	-	<b>800530</b>
800482	5004587	5005070	-	<b>800531</b>
800501	5004543	5005071	Sterling	<b>800532</b>

