

Technical Bulletin

Bulletin No.: PRO-09-04 Effective Date: 5/20/77 Page: 1 of 1

Subject: **288702 FD-1 Fan Clutch Installation / White Road Boss I**

288702 Fan Clutch has been installed on many new 1976-77 White "Road Boss I" equipped with Cummins NTC series in-line engines.

We have been advised by White that a potential clearance problem exists. As the lining wears down, the fan blade will move back until it eventually will interfere with an accessory drive pulley.

The addition of a ½" spacer, piece number 292310 between the fan and Fan Clutch resolves the problem. It is White's intent to notify their dealer network of the necessity of the modification.

The purpose of the bulletin is to alert you of the situation, so that you can service any requirements in your area.

Adequate stocks of 292310 spacers are available at Branch Plants.

