## Part Number Update

Bendi

Bulletin No: PNU-133-000 Effective Date: January 17, 2009 Cancels: N/A Page: 1 of 1

## Subject: Discontinuance of Bendix<sup>®</sup> SB-1<sup>™</sup> Actuators

Bendix Spicer Foundation Brake LLC is discontinuing the availability of the SB-1™ actuators and service replacement components. The time line below outlines the phase-out process.

Prior to February 14, 2009: Orders will be accepted until February 14, 2009 or until current inventories are depleted. All Bendix Services will be available.

After February 14, 2009: All Bendix Technical and Customer Support will continue to be available for the listed products until December 31, 2009. Orders will be processed for items in inventory.

After December 31, 2009: Bendix Technical Support (SWAT) will be available in support of the Bendix® product in the field.

## Discontinued SB-1<sup>™</sup> Spring Brake Assembly Part Numbers

SB-1 <sup>™</sup> Actuator Part No.		SB-1 <sup>™</sup> Actuator Part No.
530066	] [	275787
530029	] [	277917
530015	] [	279847
530023	] [	279283
276180	] [	280108
275787N	] [	280108N
275788	] [	280080
275789N		