

Part Number Update

Bulletin No: PNU-085-000-A

Effective Date: 9/1/02

Cancels: NA

Page: 1 of 1

Subject: Diaphragm Obsolescence and Chamber Supercession

The following diaphragms have been obsoleted and where applicable superceded by the part number listed. Where this obsolescence has affected a brake chamber that supercession has been listed as well.

Diaphragm description	Obsolete PN	Superceded by PN	Chamber PN obsoleted	Superceded by	
Diaphragm (shifter)	234330	none	224734	none	
Type F	111435	none	-	-	
Type G	111748	210816	223115	none	
Type F	200630	none	-	-	
Type E	237562	none	-	-	
Type 9 roto	234371	231472	224875	223859	} replacement diaphragms are not low temp SBR rubber, but regular SBR rubber
Type 36 roto	234376	231534	-	-	
Type 50 roto	234377	231491	284927	275244	
			288353	285577	
Type 30 roto	242486	none	-	-	
Type 16 service diaphragm	112542	234189	-	-	