

Part Number Update

Bulletin No: PNU-224

Effective Date: February 3, 2016 Cancels: NA

Page: 1 of 1

Subject: **New Bendix® ADB22X™ Air Disc Brake Standard Moly Conventional Rotor Part Numbers**

This Bulletin is to announce that new Bendix® ADB22X™ rotor part numbers have been released to replace two that have been obsoleted.

Obsolete Part Number	Order this Replacement Part Number
802081	K038573
802082	K038574

The new part numbers are compatible for fit and function.

To learn more please contact your Bendix Account Manager, visit www.foundationbrakes.com, or call:

1-800-AIR-BRAKE (1-800-247-2725, option 2).



Bendix® ADB22X™ Standard Moly Conventional Rotors.
Includes: bolts with washers.

Reference Documents:

For Bendix® ADB22X™ and ADB22X-V™ Air Disc Brakes download/order Bendix® Service Data Sheet SD-23-7541.

Downloads: Go to the Document Library on www.bendix.com for Service Data Sheets.

Printed Copies: Literature can be ordered directly from the on-line Bendix Literature Center. To register or to access your existing account, visit www.foundationbrakes.com and click on the "Marketing Center" tab at the top of the home page, or use the link on www.bendix.com.



Log-on and Learn from the Best

On-line training that's available when you are —24/7/365.
Visit www.brake-school.com.