

Part Number Update

Bulletin No: PNU-030-000-B

Effective Date: 3/10/00

Cancels: N/A

Page: 1 of 1

Subject: **BENDIX HYDRAULIC SERVICE PARTS FOR BOSCH PIN-SLIDE**

Introducing: Bendix Hydraulic Service Parts for Bosch Pin-Slide Disc Brakes

Bendix Commercial Vehicle Systems now offers repair parts to service Bosch pin-slide hydraulic disc brakes. These Bosch brakes, also known as Navistar DiamondLife™ disc brakes, were first released on Navistar applications in 1998.

The Bendix Disc Pads utilize the “HD” friction formulation, already popular with fleets operating medium-duty school buses and trucks with hydraulic disc brakes.

The following Bendix part numbers are available March 17, 2000. Please contact your service plant to place orders.

Bendix Part	Description	Piston Diameter	Replaces Navistar Part
MKD786A	Bendix Disc Pad Set	66mm	2501842C91
55849	New Caliper Assembly	66mm	2502839C91
MKD786	Bendix Disc Pad Set	73mm	2501841C91
55850	New Caliper Assembly	73mm	2501838C91

