

Part Number Update

Bulletin No: PNU-049-000-A

Effective Date: 3/01/01

Cancels: N/A

Page: 1 of 3

Subject: NEW MC-30 TRAILER ABS PART NUMBER CROSS REFERENCE

The new MC-30 Trailer ABS system now in production features PLC4Trucks mandated for all new trailers manufactured beginning March 1, 2001. This new system also features additional configurations such as **2S2M** and **4S2M** and **side control** for a wider range of trailer applications. A new system for **dollies** is also released.

The following new part numbers are now available:

ABS Assembly	Tank/Nipple Mount	Control Type	Part No.	Service Part No.
MC-30	2S/1M	Dolly-Axle	5008502	800736
MC-30	2S/2M	Side	5007645	800736
MC-30	2S/2M	Axle	5008503	800736
MC-30	4S/2M	Side	5007642	800736
MC-30	4S/2M	Axle	5008504	800736
MC-30	2S/1M - w/ PLC	Axle	5007643	800737
MC-30	2S/1M - w/ PLC	Dolly-Axle	5008505	800737
MC-30	2S/2M - w/ PLC	Side	5007646	800737
MC-30	2S/2M - w/ PLC	Axle	5008506	800737
MC-30	4S/2M - w/ PLC	Side	5007644	800737
MC-30	4S/2M - w/ PLC	Axle	5008507	800737
	Bracket/Frame Mount	Control Type	Part No.	Service Part No.
MC-30	2S/2M	Side	5008267	800819
MC-30	2S/2M	Axle	5008534	800819
MC-30	4S/2M	Side	5008264	800819
MC-30	4S/2M	Axle	5008535	800819
MC-30	2S/1M, 270° ECU Rotation	Dolly-Axle	5009526	801104
MC-30	2S/1M - w/ PLC	Axle	5008265	800820
MC-30	2S/1M - w/ PLC	Dolly-Axle	5008536	800820
MC-30	2S/2M - w/ PLC	Side	5008268	800820
MC-30	2S/2M - w/ PLC	Axle	5008537	800820
MC-30	4S/2M - w/ PLC	Side	5008266	800820
MC-30	4S/2M - w/ PLC	Axle	5008538	800820
MC-30	2S/1M - w/ PLC, 270° ECU Rotation	Dolly-Axle	5009157	801033

ECU Only	Available for service replacement only	Control Type	Part No.	Service Part No.
EC-30T	ECU (Default 4S/2M)	(Default) Side	5004357	800734
EC-30T	ECU - w/ PLC (Default 4S/2M)	(Default) Side	5004358	800735
Modulator Only				
			Part No.	Service Part No.
M-30T	Tank Mount		5007660	800741
M-30T	Tank Mount w/ ECU Bracket		5007658	800740
M-30T	Bracket Mount		5008271	800821
ECU Pigtail				
			Part No.	Service Part No.
MC-30	2S/1M - (18in.)		5006240	800775
MC-30	2S/1M - (60in.)		5007819	800776
MC-30	2S/1M - (120in.)		5007820	800777
MC-30	2S/1M - (180in.)		5007821	800778
MC-30	2S/1M - (234in.)		5007822	800779
MC-30	2S/1M - (18in.) w/diagnostic		5007823	800780
MC-30	2S/1M - (60in.) w/diagnostic		5008731	800956
MC-30	2S/1M - (120in.) w/diagnostic		5008732	800957
MC-30	2S/1M - (180in.) w/diagnostic		5008753	800935
MC-30	2S/1M - (234in.) w/diagnostic		5008756	800936
MC-30	2S/1M - (18in.) w/diagnostic, aux		5007824	800781
MC-30	2S/2M - (18in.)		5007825	800782
MC-30	2S/2M - (60in.)		5008757	800937
MC-30	2S/2M - (120in.)		5008758	800938
MC-30	2S/2M - (180in.)		5008759	800939
MC-30	2S/2M - (234in.)		5008760	800940
MC-30	2S/2M - (18in.) w/diagnostic		5007826	800783
MC-30	2S/2M - (60in.) w/diagnostic		5008761	800941
MC-30	2S/2M - (120in.) w/diagnostic		5008762	800942
MC-30	2S/2M - (180in.) w/diagnostic		5008754	800943
MC-30	2S/2M - (234in.) w/diagnostic		5008763	800944
MC-30	2S/2M - (18in.) w/diagnostic, aux		5007827	800784
MC-30	4S/2M - (18in.)		5007828	800785
MC-30	4S/2M - (60in.)		5008764	800945
MC-30	4S/2M - (120in.)		5008765	800946
MC-30	4S/2M - (180in.)		5008766	800947
MC-30	4S/2M - (234in.)		5008767	800948
MC-30	4S/2M - (18in.) w/diagnostic		5007829	800786
MC-30	4S/2M - (60in.) w/diagnostic		5008768	800949
MC-30	4S/2M - (120in.) w/diagnostic		5008769	800950
MC-30	4S/2M - (180in.) w/diagnostic		5008755	800951
MC-30	4S/2M - (234in.) w/diagnostic		5008770	800952
MC-30	4S/2M - (18in.) w/diagnostic, aux		5007830	800787
Remote Modulator Harness				
			Part No.	Service Part No.
M-30T	Remote Modulator Harness (24 in.)		5009216	801045
M-30T	Remote Modulator Harness (36 in.)		5009217	801046

M-30T	Remote Modulator Harness (72 in.)		5007831	800788
M-30T	Remote Modulator Harness (180 in.)		5007832	800789
M-30T	Remote Modulator Harness (240 in.)		5009218	801047
M-30T	Remote Modulator Harness (300 in.)		5009219	801048
M-30T	Remote Modulator Harness (360 in.)		5009220	801049
Remote Diagnostic Harness				
			Part No.	Service Part No.
MC-30	Remote Diagnostic Harness w/cap (72 in.)		5009193	801038
MC-30	Remote Diagnostic Harness w/cap (84 in.)		5009194	801039
MC-30	Remote Diagnostic Harness w/cap (120 in.)		5007833	800790
Speed Sensor Lead Extensions				
			Part No.	Service Part No.
WS-20	Deutsch - 240 in.		5009221	801051
WS-20	Deutsch - 300 in.		5009222	801052
WS-20	Deutsch - 360 in.		5009223	801053

