

# Part Number Update

Bulletin No: PNU-066-000-B

Effective Date: 9/1/01

Cancels: PNU-052-000-A

Page: 1 of 2

**Subject: ABS ECU NEW RELEASE**

All part numbers for the ABS Electronic Control Unit (ECU) are being changed to reflect some software and hardware changes to the ECU. This new release of the EC-30 will incorporate a new microprocessor (due to supplier availability) and new software improvements including added functionality of an electronic logbook for storing OEM and FLEET maintenance data. This changeover will occur beginning in November after inventory depletion of existing units. This new release is backward compatible with all previous EC-17 and EC-30 as noted.

As before, the EC-30 will be available for service as an ECU only. Service parts for valves and brackets used in assemblies are provided. Please prepare for this required change.

**Service Part Numbers**

Previously  
Obsoleted  
EC-17 PN's

PARTS  
NUMBERS  
TO  
OBSOLETE

**NEW PART  
NUMBERS  
TO USE**

Model	EC-17 2.30 Svc PN 2	EC-30 Svc ECU (v1.08.01)	EC-30 Svc ECU (v2.0)	Svc Valve Assm	Svc Valve Kit	Bracket Kit
AT-1	800886	800854	<b>801236</b>	800335	109368	n/a
AT-1	800860	800854	<b>801236</b>	65516	109368	n/a
AT-2	800886	800854	<b>801236</b>	800334	109359	n/a
CR-17	800886	800854	<b>801236</b>	800297	109368	n/a
CR-17	800860	800854	<b>801236</b>	800179	109368	n/a
CR-17	800886	800854	<b>801236</b>	800605	109368	n/a
CR-17DC	not req'd	not req'd	<b>not req'd</b>	not req'd	not req'd	n/a
CR-17N	800860	800854	<b>801236</b>	800179	109368	n/a
CR-17N	800860	800854	<b>801236</b>	800466	109368	n/a
CR-18	800886	800854	<b>801236</b>	800299	109359	n/a
EC-16	800967	800854	<b>801236</b>	n/a	n/a	5004965
EC-17	800977	800852	<b>801234</b>	n/a	n/a	n/a
EC-17	800976	800853	<b>801235</b>	n/a	n/a	n/a
EC-17	800886	800854	<b>801236</b>	n/a	n/a	n/a
EC-17	800971	800854	<b>801236</b>	n/a	n/a	800108
EC-17	800860	800854	<b>801236</b>	n/a	n/a	n/a
EC-17	800965	800851	<b>801233</b>	n/a	n/a	n/a
EC-17	800966	800851	<b>801233</b>	n/a	n/a	800108
EC-17	800886	800854	<b>801236</b>	n/a	n/a	n/a
EC-17N	800860	800854	<b>801236</b>	n/a	n/a	n/a

**EC-30 con't****OEM/Service Part Numbers**

Model	Obsoloted Part Numbers		New Part Numbers	
	OEM	Service	OEM	Service
EC-30	5007720	801050	<b>5010345</b>	<b>801181</b>
EC-30 w PLC	5009173	800694	<b>5010358</b>	<b>801180</b>
EC-30 w PLC	5009235	800694	<b>5010359</b>	<b>801180</b>
EC-30	5009236	801050	<b>5010360</b>	<b>801181</b>
EC-30	5007775	801050	<b>5010318</b>	<b>801181</b>
EC-30 w PLC	5009583	800694	<b>5010320</b>	<b>801180</b>
EC-30 w PLC	5009204	801073	<b>5010319</b>	<b>801239</b>
EC-30	5007768	800761	<b>5010314</b>	<b>801225</b>
EC-30	5007769	800761	not req'd	<b>801225</b>
EC-30 w PLC	5008857	801075	<b>5010316</b>	<b>801227</b>
EC-30 w PLC	5008858	801075	not req'd	<b>801227</b>
EC-30	5009133	800854	<b>5010692</b>	<b>801236</b>
EC-30	5009190	800854	<b>5010693</b>	<b>801236</b>
EC-30	5009026	800851	<b>5010685</b>	<b>801233</b>
EC-30	5009046	800851	<b>5010687</b>	<b>801233</b>
EC-30	5009040	800854	<b>5010686</b>	<b>801236</b>
EC-30	5009048	800852	<b>5010689</b>	<b>801234</b>
EC-30	5009047	800853	<b>5010688</b>	<b>801235</b>
EC-30	5009049	800854	<b>5010690</b>	<b>801236</b>
EC-30	5009050	800854	<b>5010691</b>	<b>801236</b>
EC-30	5006796	800768	<b>5010301</b>	<b>801197</b>
EC-30	5006797	800769	<b>5010302</b>	<b>801198</b>
EC-30	5008379	800844	<b>5010303</b>	<b>801206</b>
EC-30	5008380	800843	<b>5010304</b>	<b>801205</b>
EC-30	5005927	800804	<b>5010305</b>	<b>801199</b>
EC-30	5005928	800805	<b>5010306</b>	<b>801200</b>
EC-30	N/A	800806	N/A	<b>801201</b>
EC-30	5008376	800850	<b>5010308</b>	<b>801209</b>
EC-30	5008377	800849	<b>5010309</b>	<b>801208</b>
EC-30	5008378	800848	<b>5010310</b>	<b>801207</b>

