## Part Number Update

Bendix

Page: 1 of 1

Bulletin No: PNU-118-000 Effective Date: July 1, 2008 Cancels: N/A

## Subject: Bendix® AD-IS® / AD-IP® Air Dryer Purge Valve Assembly Replacement Kit

Purge Valve Maintenance Kit piece number **5018313** has been obsoleted and superseded by Purge Valve Assembly Replacement Kit piece number **K022105**. See kit contents comparison below.

For additional information refer to Technical Bulletin TCH-008-043.

Obsoleted: Superseded To: Purge Valve Maintenance Kit Piece Number 5018313 Purge Valve Assembly Replacement Kit Piece Number K022105 ਨਾ AD-IS® or AD-IP® AD-IS® or AD-IP® Air Dryer Body Air Dryer Body Installation Ring **Purge Piston** Purge Piston Quad-Ring (not included) Small O-ring Large O-ring Large O-ring Purge Valve Assembly Retaining Ring **Retaining Ring** Purge Valve Maintenance Kit Contents: Purge Valve Assembly Replacement Kit Contents: Qty. Description Qty. Description Large O-ring 1 Large O-ring 1 Small O-ring (installed) Small O-ring 1 1 Lubricant (not shown) Lubricant (not shown) 1 1 Retaining Ring Retaining Ring 1 1 Purge Piston Quad-Ring Purge Valve Assembly (with protective cap) 1 1 1 Installation Ring