

# Part Number Update

Bulletin No: PNU-099-000-A

Effective Date: 7/05/04

Cancels: NA

Page: 1 of 1

Subject: CORE CHARGE CHANGE ON RELINED HYDRAULIC SHOES

Effective July 5, 2004 core charges associated with some Bendix® relined hydraulic shoes will be eliminated.

The process for the elimination of core charges is as follows:

- Bendix Hydraulic relined shoe prices will no longer include a core charge effective July 5, 2004.
- A new pricing structure for the outright relined shoes will be instituted beginning July 5, 2004.
- "RAF" prefixed shoes will retain the same part number.
- A small number of shoes with the "R" prefix will be superseded to an outright relined "RAF" part number going forward.
- Current shoe core returns must be shipped to BCVS no later than November 15th.
- All returns will be based upon customer core eligibility.
- Any shipments made after November 15th will not be credited to your core account and will be disposed of at BCVS's discretion.
- Your BCVS Account Manager will provide you with details regarding your current return eligibility.
- To ensure timely and accurate credit processing, core returns must be made using the standard BCVS Core Return Memo form (CRM) BW2313.
- Core credits will be issued through November 30, 2004 on brake shoes returned as part of annual stock adjustments.

The following parts are affected: