

Part Number Update

Bulletin No: PNU-084-000-A

Effective Date: 8/1/02

Cancels: NA

Page: 1 of 1

Subject: New AD-9 Reman Air Dryer

This release combines the AD-9, mounting bracket kit and wiring harness kit into a single kit, ordered under a single part number. While the elements of this new kit have been available individually, customers have clearly indicated a need for a complete kit. When changing out competitive dryers, the dryer, bracket kit and wiring kit are all needed. Release of this new part number consolidates and simplifies ordering and receiving when upgrading air brake systems from non-Bendix air dryers to the Bendix AD-9.

<u>Part Number</u>	<u>Model</u>	<u>Description</u>
5009378X	AD-9	Reman 12V Air Dryer w/bracket and harness

