

Bulletin No.: PRO-05-07

Effective Date: 5/15/80 Cancels: PRO-05-07 dated 5/1/80

Page: 1 of 1

Subject: AUTOMATIC SLACK ADJUSTERS (RETROFIT) - FORD "L" SERIES DRIVE AXLES

The information furnished to Bendix H.V.S.G. that prompted us to issue bulletin PRO-05-7 dated 5-1-80 has been proven incorrect. Therefore, please disregard and destroy the bulletin.

We do, however, recommend that all installations of automatic slack adjusters be carefully checked for clearance and proper operation.

We regret any inconvenience.